23043-01-001

St. John's Convent, New Street, Rathangan

ROAD SAFETY AUDIT STAGE 1/2

Septmeber 2023



CONSULTING

7, Ormonde Road Kilkenny R95 N4FE

Tel: 056 7795800 info@roadplan.ie www.roadplan.ie

1. INTRODUCTION

- 1.1 This report describes a Stage 1 / 2 Road Safety Audit carried out at the proposed development St. John's Convent, New Street, Rathangan on behalf of Walsh Associates. The audit was carried out on 18th July 2023 in the offices of Roadplan Consulting, Kilkenny.
- 1.2 The audit team members were as follows:
 - George Frisby, BE CEng MIEI
 Auditor Number GF51255
 - Richard Frisby, BSc AEng MIEI Auditor Number RF1337391
 - Jince Philip Zachariah, PhD CEng.
 Observer
- 1.3 Both audit team members visited the site on the 11th July 2023. The audit comprised an examination of the drawings relating to the scheme supplied by Walsh Architects and an examination of the site.
- 1.4 The proposed development features 24 residential units at New Street (R414), Rathangan, Co. Kildare.



- 1.5 The speed limit of road at the site entrance is 50 km/h.
- 1.6 This Stage 1 / 2 Audit has been carried out in accordance with the relevant sections of TII GE-STY-01024. The team has examined only those issues


within the design relating to the road safety implications of the scheme and has therefore not examined or verified the compliance of the design to any other criteria.

- 1.7 All problems described in this report are considered by the audit team to require action in order to improve the safety of the scheme and minimise accident occurrence.
- 1.8 Appendix A describes the audited drawings.

2. STAGE 1 / 2 AUDIT

2.1 Problem

Intervisibility between drivers of vehicles exiting the proposed development and pedestrians travelling along the existing footpath may be restricted by the proposed boundary walls and piers either side of the access. A lack of adequate intervisibility at this location may contribute to a pedestrian collision at the proposed access.




Recommendation

Revise the layout to ensure that adequate intervisibility between drivers of vehicles exiting the proposed development and pedestrians travelling along the existing footpath is provided.

2.2 **Problem**

The proposed pedestrian access to the development from the R414 adjacent to the vehicular access appears to be narrow. As a result, mobility impaired pedestrians may not be able to use this access and instead access the proposed development via the vehicular access which would increase the risk of a collision at this location.




Recommendation

Ensure that the proposed pedestrian access is sufficiently wide to cater for mobility impaired pedestrians.

2.3 **Problem**

A minibus set-down area is proposed within the development on the west side of the access road with a footpath to the rear of the set-down area. However, the main footpath linking to the housing units within the development is located on the east side of the access road and an appropriate link to this footpath is not shown to be provided from the minibus et-down area. A lack of an appropriate footpath link may result in pedestrians travelling along the access road where they would be at an increased risk of being struck by a passing vehicle.



Recommendation

Provide an adequate footpath link from the minibus set-down to the proposed footpath on the east side of the access road.

2.4 Problem


A minibus set-down area and parking spaces are proposed immediately within the development in close proximity to its junction with the R414. Intervisibility between drivers of vehicles entering the proposed development and drivers of vehicles turning to and from these parking spaces may be restricted by the proposed roadside boundaries. A lack of adequate intervisibility may contribute to a collision at this location.

Recommendation

Provide measures to ensure that adequate intervisibility between drivers of vehicles entering the proposed development and drivers of vehicles turning to and from these parking spaces is provided. Such measures could include lowering the roadside boundaries, provision of a raised crossing at the proposed access etc.

2.5 Problem

At the proposed access the kerbline is shown to be returned with priority given to drivers of vehicles entering and exiting at the access. Dropped kerbs and tactile paving are not shown to be provided to cater for mobility impaired pedestrians crossing at the proposed access. A lack of adequate pedestrian facilities may increase collision risk at this location.




Recommendation

In conjunction with recommendation 2.4 above, provide priority to pedestrians at the access. Alternatively, provide dropped kerbs and tactile paving either side of the access.

2.6 **Problem**

A footpath is not shown to be provided to accommodate pedestrians travelling to and from the parking spaces on the south side of the turning head within the proposed development. A lack of an appropriate footpath link may result in pedestrians travelling along the access road where they would be at an increased risk of being struck by a passing vehicle.



Recommendation

Provide an adequate footpath link from these parking spaces to the proposed footpath on the east side of the access road.

3. AUDIT TEAM STATEMENT

3.1 We certify that we have examined the drawings listed in Appendix A and have inspected the site. This examination has been carried out with the sole purpose of identifying any features of the design that could be removed or modified to improve the safety of the scheme.

Signed	George Frisby
Date18 th July 2023	
Signed Richard Frisby	Richard Frisby


Date 18th July 2023

APPENDIX A

List of Drawings Examined

The following drawings have been provided electronically in PDF format by Walsh Associates:

Drawing number	Rev	Drawing title
P-004		PROPOSED SITE LAYOUT PLAN
SK-010A		SITE LOCATION MAP




ORDNANCE SURVEY LICENCE NUMBER CYAL50314133 OS Sheet Nos. 3553-B ITM Co-ordinates X = 667373.2126 Y =719600.2004 LEGEND REVISIONS AFTER LAST PLOT: walsh associates


ALL CONSTRUCTION METHODS, MATERIALS, SERVICES & INSTALLATIONS TO BE IN ACCORDANCE WITH ALL IRISH BUILDING REGULATIONS AND CODES OF PRACTICE AT THE TIME OF CONSTRUCTION, IF IN DOUBT ASK!

SITE BOUNDARY = 6761.7 m² (0.676 ha)

OJECT:	Development at St John's Convent,	DATE: 04/05/2022	SCALE: 1:2500@A3	
		DRAWN: RN	JOB NO.	DWG. NO.
	Co. Kildare	K:\Dr\20003\SK	20003	SK-010A
RAWING:	SITE LOCATION MAP	Stage:	Revision:	
		PRE-PLANNING		







SAFETY AUDIT FEEDBACK FORM

Scheme: Proposed Development at St. John's Convent, New Street, Rathangan

Document Number: 23043-01-001

Audit Stage: Stage 1 / 2 RSA

Date Audit Completed: 18th July 2023

Paragraph		To Be Completed By Designer		
No. in Safety Audit Report	Problem accepted (yes/no) Recommended measure accepted (yes/no)		Describe alternative measure(s). Give reasons for not accepting recommended measure. Only complete if recommended measure is not accepted.	Alternative measures or reasons accepted by auditors (yes/no)
2.1	YES	YES		
2.2	YES	YES		
2.3	YES	YES		
2.4	YES	YES		
2.5	YES /	YES		
2.6	YES	KES		

Safety Audit Signed off Design Team Leader Print Name	Date 200, 202
Safety Audit Signed off Employer Print Name **EVIN Name** Print Name** **EVIN Name** **EVI	Date 30/4/23
Safety Audit Signed off	

Please complete and return to:

Print Name George Frisby

Roadplan Consulting, 7, Ormonde Road

Kilkenny

E-mail: info@roadplan.ie